### Work Order ID 58305

Page 1

Insp.

Stamp

May 3, 2010 11:19:20 AM D4019-3 Item ID: Accept Setup Start **Revision ID:** Stop Rib Item Name: Start Qty: 9.00 **Start Date:** 03/05/2010 **Cust Item ID: Required Date:** 13/05/2010 Req'd Qty: 9.00 **Customer:** Reference: Start Date: 10-5-03 Tooling: Run **Process Plan:** Approvals: Date: Stop QC: Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Draw Draw Plan Accept Reject Reject Work Center ID Description **Run Hours** Number Rev. Code Qty Qty Number **Revision Nbr Draw Nbr** D4019 C 100 0.00 Large Fab 0.00 Memo SAD 10-05-04 Large Fab 1- Cut tube as per dwg D4019 2- remove identification marks and deburr 110 QC5- Inspect part completeness to step on W/O 0.00 0.00 Memo Quality Control

120

Packaging

Packaging

Identify as per dwg & Stock Location:

Memo

Dart	<b>Aerospace</b>	Ltd

W/O:			٧	VORK ORD	ER CHANG	ES	···········					
DATE	STEP	PRO	OCEDURE CH	IANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
-			<u>-</u>									
						<u>.</u>						
			Fault Category: NCR: Yes No DQA									
	Resolution: Disposition: QA: N/C Closed:						sed:		Date:	***************************************		
NCR:			WORK OR	DER NON-	CONFORM	ANCE	(NCR	)				
DATE	STEP	Description of NC	Corrective Action Section B Verif					Verifica	ation	Approval	Approval	
	012.	Section A	Initial Chief Eng		n Description Chief Eng		Sign & Date	Section	n C	Chief Eng	QC Inspector	
				,								
L,												
							-					
1												
	L	1						1				

#### Work Order ID 58305

May 3, 2010 11:19:20 AM



Page 2

Item ID:

D4019-3

Accept

Setup Start

Stop



**Revision ID:** 

Item Name:

**Start Date:** 

Rib

03/05/2010 Start Qty: 9.00

**Required Date:** 13/05/2010

Req'd Qty: 9.00



**Cust Item ID:** 

**Customer:** 

Reference:

A	nn	ro	Va	Is	•

Process Plan:

Operation

Description

Date:\_\_\_\_\_

Tooling:

Date:

Run

Start



QC:

Date:

SPC (Y/N):

Set Up/

**Run Hours** 

Date:

Stop



Sequence ID/ Work Center ID

130

Memo

QC21- Final Inspection - Work Order Release

0.00

Draw Number

Draw Plan Code Rev.

Accept Qty

Reject Qty

Reject Insp. Number

Stamp

Quality Control

0.00

1.

MF 10-5-4

### **Dart Aerospace Ltd** W/O: **WORK ORDER CHANGES** Approval Chief Eng / **Approval** DATE STEP **PROCEDURE CHANGE** By Date Qty QC Inspector Prod Mgr Part No: \_\_\_\_\_\_ PAR #: \_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_ Date: \_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_ WORK ORDER NON-CONFORMANCE (NCR) NCR: **Corrective Action** Section B **Description of NC** Verification DATE **STEP** Approval Approval Sign & Initial **Action Description** Section A QC Inspector Section C Chief Eng Chief Eng Chief Eng Date

#### **Picklist Print**

May 3, 2010 11:19:25 AM

Work Order ID: 58305

Parent Item: D4019-3

Parent Item Name:

Rib

Comments:

IPP RevA: new issue DD 10.01.25 verified by:EC IPP Rev:C as per dwg revC

per dwg revA 10.03.15 verified by:EC

DD 10.04.20 verified by:EC

Start Date: 03/05/2010

Start Qty: 9.00

**Required Date: 13/05/2010** 

Required Qty: 9.00

Component Item ID/ M6061T6TS0.750W.06

Replacement Mfg/

Purchased

Bin No

Primary

Last

Route 100

IPP Rev:B as

Unit of

Qty on 77.6752

Qty per Kit Qty 1.75

Date

Status

Page 1

2




6061-T6 SQ Tube .75 x .75 x .062W

Location	Loc Qty	Loc Code	
MAT06	77.6752		
103069	38.0526		
104422	15.5263		
16441	4.07		
9671	20.0263		

M114573


-> 1.75 ×9=15.75

W/O:			WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
9,4.				- 17								
Part No: PAR #:		R #: Fault Category: NCR:			l: Yes I	No <b>DQA</b>	A: Date:					
				Disposition: QA: N/C Closed:					•			
NCR:			WORK ORDE	ER NON-CONFORM	ANCE	(NCR	)					
DATE	STEP	Description of NC	Corrective Action Section B			0:	- Verifica	ation	Approval	Approval		
		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector		
								i				
					:							
		·										




Dart Aerospace I	Ltd
------------------	-----


W/O:	<u>-</u>		144	ORK ORDER OUANG	250			+				
₩/∪.	1		VV	ORK ORDER CHANG	JES .	· · · · · · · · · · · · · · · · · · ·	·····	ļ				
DATE	STEP	PRO	PROCEDURE CHANGE By Date				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
					F 474							
Part No: PAR #:			Fault Category: NCR: Yes No [				No <b>DQA</b>	DQA: Date:				
	Re	esolution:	Dispositi	Disposition: QA: N/C					Date:	<del></del>		
NCR:			WORK ORD	ER NON-CONFORM	ANCE	(NCR	)					
DATE	STEP	Description of NC	Corrective Action Section B Ver			Verifica	erification	Approval	Approval			
	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector		
								1		-		
									į			
				·								
NOTE 5										}		



		•								
W/O:			WC	RK ORDER CHANG	ES					×
DATE	STEP	PR	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		,								
								<u> </u>		
٠.,										
Part No:PAR #:			Fault Cate	jory:		Date: _				
		lesolution:								
NCR:			WORK ORDE	R NON-CONFORMA	NCE	(NCR	)			
DATE	CTED	Description of NC	Corrective Action Section B				Verific	eation	ation Approval	
DATE	SIEP	STEP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section C		Chief Eng	Approval QC Inspector
,		:								
		>					<del>                                     </del>			
					•					
l .	1	1	1 1		i		I		I	l·



		<del></del>									
W/O:			WO	RK ORDER CHANGI	ES						
DATE	STEP	PR	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
			·								
Part No:		PAR #:	Fault Categ	ory:	NCR: Yes No DQA: Date:						
	Re	solution:	Disposition	:	QA: N/C	Closed:		Date: _			
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NC	R)					
DATE	STEP	Description of NC	Corrective Action Section B			Verifi	cation	cation Approval	Approval		
		Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Dat		tion C	Chief Eng	QC Inspector		
									,		
							·		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		



	•									T		
W/O:			WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE				y	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
									n Tusan na			
Part No:PAR #:			Fault Cate	jory:	NCR: Y	A:	Date:					
Resolution:			Disposition	:	QA: N/	C Clo	sed:		Date: _			
NCR:			WORK ORDE	R NON-CONFORMA	NCE (N	ICR)						
DATE	STEP	Description of NC	Initial	n B	an 0	Verification						
		Section A	Chief Eng	Action Description Chief Eng		gn & Oate	Secti	on C	Chief Eng	QC Inspector		
									1			
•												
	-									•		
			1 1				1			<b>l</b> .		